Change Log Version 1.7.5 (09.2023)
Major performance and stability improvements.

- **New:** Access to the web interface via host name possible

Change Log Version 1.7.4 (11.2022)

- **Fixed:** ETS project could not be imported

Change Log Version 1.7.3 (11.2022)
Systemic relevant improvements

- **New:** New APPMODULE Easywave Variant
- **Implemented:** Implemented: ETS-Inside configuration page: Note on discontinued
- **Fixed:** After interruption of the network connection, the APPMODULE was not accessible under certain circumstances
- **Fixed:** System time was not displayed correctly after restart for some time zones

Change Log Version 1.7.2 (03.2022)
NOTE: Please install the update 1.7.2 with the Mozilla Firefox or Apple Safari browser.

- **Implemented:** Adjustments in the update process
- **Implemented:** Default DNS server on delivery
- **Implemented:** Data point type DPT1.024 added to language file

Change Log Version 1.7.1 (12.2021)
Closes a security vulnerability in the Log4j framework used

Change Log Version 1.7.0 (11.2021)
System relevant improvements

- **New:** HOOC remote access
- **New:** Activation page for HOOC remote access

Change Log Version 1.6.2 (07.2021)

- **NEW:** Virtual KNX group address range can be deactivated
- **NEW:** Address range for the virtual KNX group addresses adjustable
- **NEW:** Validation of the entered network mask for plausibility
- **NEW:** Data point type DPT 5.005
- **Implemented:** Improvement of the display on iOS devices

- **Fixed:** Correction of scaling for data point type DPT5.003
- **Fixed:** Upload ETS Inside Server Backup
- **Fixed:** Saving the configuration for the EnOcean variant

- System relevant improvements

Change Log Version 1.6.1 (10.2020)

- **Fixed:** ETSinside Backups hochladen

Change Log Version 1.6.0 (07.2020)

- **NEW:** Integration into the terminal configurator incl. Smart Home APP purchase

Change Log Version 1.5.4 (06.2020)

- **Fixed:** The EnOcean Live Monitor could not establish a connection
- **Fixed:** ETS license upload failed

Change Log Version 1.5.3 (06.2020)

- **Fixed:** Installed apps were not displayed under certain circumstances

Change Log Version 1.5.2 (06.2020)

- **Implemented**: Extended time zone selection
- **Implemented**: ETS Inside: Backup management optimized
- **Fixed**: System coupling did not work
- **Fixed**: APP MODULE has occasionally sent double routing telegrams

Change Log Version 1.5.1 (03.2020)

- internal version

Change Log Version 1.5.0 (12.2019)

- **NEW:** ETS Inside Server (license required)
- **Implemented:** Improved internal DNS server management
- **Implemented:** Revision of the display of group addresses and permissible input of group addresses; 2-digit, 3-digit, integer

- **Implemented:** Instance memory button was replaced by button "Save" and button "Save and close".
- **Fixed:** Selection of group addresses was not possible when configuring list elements.

- Internal software components updated

Change Log Version 1.4.1 (03.2019)

- **Implemented:** Reference to virtual group addresses, group addresses are used ≥ Main group 16 appears next to the address field a reference
- **Fixed:** Button "Update search" is locked during the search process
- **Fixed:** Installed apps were not displayed when an instance was defective

- Internal software components updated

Change Log Version 1.4.0 (02.2019)

- **NEW:** KNX Project Import
- **NEW:** Automatic update search can be activated
- **NEW:** APPMODULE downloads and installs App-Updates on demand
- **Fixed:** Log level of apps cannot be changed properly by dropdown
- **Fixed:** No learning telegram for the EEP A5-10-05 can be sent in the EnOcean configuration

Change Log Version 1.3.8

- **Implemented:** HTTP- or HTTPS- interface for feedback to apps from outside the network
- **Fixed:** List element Copy button

- Performance Improvements

Change Log Version 1.3.7

- **Implemented:** Eltako Dimming (80-02-01): Eltako FUD14 / FUD61 / FDDT65B (Bidirectional; Feedback Device)
- **Implemented:** Eltako bus actuator for shading elements and roller shutters (80-03-01): Eltako FSB14 / FSB61 (bidirectional; feedback device)
- **Implemented:** Eltako PIR Sensor (80-04-01): devices: Eltako FBH65S
- **Implemented:** Eltako Presence Tracker (80-07-01): Eltako TF-TTB
- **Implemented:** Light, temperature and presence sensor (EEP a5-08-01)
- **Implemented:** Temperature, setpoint, presence detector (EEP a5-10-05) (feedback device)
- **Implemented:** Input contact (EEP d5-00-01)
- **Implemented:** RPS 2-Rocker (EEPf6-02-01)

- **Implemented:** Window handle (EEP f6-10-00)
- **Implemented:** General stability and performance improvements
- **Fixed:** EnOcean Editor bidirectional teaching

Change Log Version 1.3.6

- internal version

Change Log Version 1.3.5

- **NEW:** Remote Support
- **New:** Automatic generation of group addresses in apps
- **Implemented:** general stability and performance improvements
- **Fixed:** Problems after changing IP addresses

Change Log Version 1.3.4

- **Implemented:** Firmware prepared for »Amazon Alexa Integration«

Change Log Version 1.3.3

- **NEW:** Tolerant handling when saving app instances with list elements that contain group addresses
- **Implemented:** Short names for app instances.
- **Fixed:** Problems when saving app instances with list elements that contain group addresses.

Change Log Version 1.3.2

- **NEW:** Warning when using group address twice in an instance

Change Log Version 1.3.1

- **NEW:** Added bidirectional devices to EnOcean Editor
- **Implemented:** overhauled EnOcean Live Monitor
- **Implemented:** Simulated EnOcean Telegrams (to teach-in virtual devices)

Change Log Version 1.3.0

- **NEW:** new user Interface

- **NEW:** new web-based EnOcean editor
- **NEW:** Integrated APPMODULE documentation in web interface
- **NEW:** Integrated App documentation (in supported apps)
- **NEW:** EnOcean-focused instance configuration (in supported apps)
- **Implemented:** variable EIS14 values for EnOcean switches
- **Implemented:** better link names in apps (in supported apps)
- **Implemented:** installed apps will be preserved after firmware update
- **Fixed:** DHCP functionality

Change Log Version 1.2.3

- **Fixed:** Potential reboots when multiple apps are installed due to overly restrictive system monitoring in version 1.2.2

Change Log Version 1.2.2

- **Fixed:** Error in DHCP IP address assignment

Change Log Version 1.2.1

- **Implemented:** Retrieving physical addresses over KNXnet/IP Tunneling (hardware variant Extension)
- **Fixed:** Errors in connection handling with ETS 5 if NAT mode is enabled
- **Fixed:** DNS issues after manually changing the DNS server
- **Fixed:** Inactive instances can only be copied accompanied by an error message
- **Fixed:** Potential reboots when multiple apps are installed due to overly restrictive system monitoring in version 1.2.0

Change Log Version 1.2.0

- **NEW:** Support for the EnOcean hardware variant, port of the EnOcean Editor from EIB**PORT**
- **Fixed:** Bug in backup mechanism for apps and instances