

ChangeLog Version 1.5.4 (06.2020)

- **Fixed:** The EnOcean Live Monitor could not establish a connection
- **Fixed:** ETS license upload failed

ChangeLog Version 1.5.3 (06.2020)

- Installed apps were not displayed under certain circumstances

ChangeLog Version 1.5.2 (06.2020)

- **Implemented:** Extended time zone selection
- **Implemented:** ETS Inside: Backup management optimized
- **Fixed:** System coupling did not work
- **Fixed:** APP MODULE has occasionally sent double routing telegrams

ChangeLog Version 1.5.1 (03.2020)

- internal version

ChangeLog Version 1.5.0 (12.2019)

- **NEW:** ETS Inside Server (license required)
- **Implemented:** Improved internal DNS server management
- **Implemented:** Revision of the display of group addresses and permissible input of group addresses; 2-digit, 3-digit, integer
- **Implemented:** Instance memory button was replaced by button "Save" and button "Save and close".
- **Fixed:** Selection of group addresses was not possible when configuring list elements.

- Internal software components updated

ChangeLog Version 1.4.1 (03.2019)

- **Implemented:** Reference to virtual group addresses, group addresses are used \geq Main group 16 appears next to the address field a reference
- **Fixed:** Button "Update search" is locked during the search process
- **Fixed:** Installed apps were not displayed when an instance was defective

- Internal software components updated

ChangeLog Version 1.4.0 (02.2019)

- **NEW:** KNX Project Import
- **NEW:** Automatic update search can be activated
- **NEW:** APPMODULE downloads and installs App-Updates on demand
- **Fixed:** Log level of apps cannot be changed properly by dropdown
- **Fixed:** No learning telegram for the EEP A5-10-05 can be sent in the EnOcean configuration

ChangeLog Version 1.3.8

-
- **Implemented:** HTTP- or HTTPS- interface for feedback to apps from outside the network
- **Fixed:** List element Copy button
- Performance Improvements

ChangeLog Version 1.3.7

- **Implemented:** Eltako Dimming (80-02-01): Eltako FUD14 / FUD61 / FDDT65B (Bidirectional; Feedback Device)
- **Implemented:** Eltako bus actuator for shading elements and roller shutters (80-03-01): Eltako FSB14 / FSB61 (bidirectional; feedback device)
- **Implemented:** Eltako PIR Sensor (80-04-01): devices: Eltako FBH65S
- **Implemented:** Eltako Presence Tracker (80-07-01): Eltako TF-TTB
- **Implemented:** Light, temperature and presence sensor (EEP a5-08-01)
- **Implemented:** Temperature, setpoint, presence detector (EEP a5-10-05) (feedback device)
- **Implemented:** Input contact (EEP d5-00-01)
- **Implemented:** RPS 2-Rocker (EEPf6-02-01)
- **Implemented:** Window handle (EEP f6-10-00)
- **Implemented:** General stability and performance improvements
- **Fixed:** EnOcean Editor bidirectional teaching

ChangeLog Version 1.3.6

- internal version

ChangeLog Version 1.3.5

- **NEW:** Remote Support
- **New:** Automatic generation of group addresses in apps
- **Implemented:** general stability and performance improvements
- **Fixed:** Problems after changing IP addresses

ChangeLog Version 1.3.4

- **Implemented:** Firmware prepared for »Amazon Alexa Integration«

ChangeLog Version 1.3.3

- **NEW:** Tolerant handling when saving app instances with list elements that contain group addresses
- **Implemented:** Short names for app instances.
- **Fixed:** Problems when saving app instances with list elements that contain group addresses.

ChangeLog Version 1.3.2

- **NEW:** Warning when using group address twice in an instance

ChangeLog Version 1.3.1

- **NEW:** Added bidirectional devices to EnOcean Editor
- **Implemented:** overhauled EnOcean Live Monitor
- **Implemented:** Simulated EnOcean Telegrams (to teach-in virtual devices)

ChangeLog Version 1.3.0

- **NEW:** new user Interface
- **NEW:** new web-based EnOcean editor
- **NEW:** Integrated APPMODULE documentation in web interface
- **NEW:** Integrated App documentation (in supported apps)
- **NEW:** EnOcean-focused instance configuration (in supported apps)
- **Implemented:** variable EIS14 values for EnOcean switches
- **Implemented:** better link names in apps (in supported apps)
- **Implemented:** installed apps will be preserved after firmware update
- **Fixed:** DHCP functionality

ChangeLog Version 1.2.3

- **Fixed:** Potential reboots when multiple apps are installed due to overly restrictive system monitoring in version 1.2.2

ChangeLog Version 1.2.2

- **Fixed:** Error in DHCP IP address assignment

ChangeLog Version 1.2.1

- **Implemented:** Retrieving physical addresses over KNXnet/IP Tunneling (hardware variant Extension)
- **Fixed:** Errors in connection handling with ETS 5 if NAT mode is enabled
- **Fixed:** DNS issues after manually changing the DNS server
- **Fixed:** Inactive instances can only be copied accompanied by an error message
- **Fixed:** Potential reboots when multiple apps are installed due to overly restrictive system monitoring in version 1.2.0

ChangeLog Version 1.2.0

- **NEW:** Support for the EnOcean hardware variant, port of the EnOcean Editor from EIBPORT

- **Fixed:** Bug in backup mechanism for apps and instances